

# nRF21540

## Revision 2

### Errata

v1.0

# Contents

- 1 nRF21540 Revision 2 Errata. . . . . 3
- 2 Revision history. . . . . 4
- 3 New and inherited anomalies. . . . . 5
  - 3.1 [7] : Current leakage via MODE pin affecting RF performance . . . . . 5
  - 3.2 [10] : Increased current consumption in Power-down state . . . . . 5



# 1 nRF21540 Revision 2 Errata

This Errata document contains anomalies and configurations for the nRF21540 chip, revision Revision 2 (QDAA-G00).

The document indicates which anomalies are fixed, inherited, or new compared to revision [Engineering C](#).

## 2 Revision history

See the following list for an overview of changes from previous versions of this document.

Version	Date	Change
nRF21540 Revision 2 v1.0	21.01.2022	<ul style="list-style-type: none"><li>• Added: No. 7. "Current leakage via MODE pin affecting RF performance"</li><li>• Added: No. 10. "Increased current consumption in Power-down state"</li></ul>

# 3 New and inherited anomalies

The following anomalies are present in revision Revision 2 of the nRF21540 chip.

ID	Module	Description	Inherited from Engineering C
7		Current leakage via MODE pin affecting RF performance	X
10		Increased current consumption in Power-down state	X

Table 1: New and inherited anomalies

## 3.1 [7] : Current leakage via MODE pin affecting RF performance

This anomaly applies to IC Rev. Revision 2, build codes QDAA-G00.

It was inherited from the previous IC revision [Engineering C](#).

### Symptoms

Current leakage via MODE pin. Both TX and RX gain, as well as LNA noise figure (NF), are affected.

### Conditions

Using pin control with MODE pin pulled to VDD.

### Consequences

Increased current leakage into MODE pin when pulled to VDD. TX and RX gain will be affected, as well as the device current consumption. Higher noise figure will impact the RX sensitivity.

### Workaround

Use one of the following:

1. 33 kΩ resistor in series on MODE pin.
2. SPI control and keep MODE pin pulled to GND.

## 3.2 [10] : Increased current consumption in Power-down state

This anomaly applies to IC Rev. Revision 2, build codes QDAA-G00.

It was inherited from the previous IC revision [Engineering C](#).

## **Symptoms**

Increased current consumption in Power-down state.

## **Conditions**

MODE pin is set high while PDN pin is set low.

## **Consequences**

Current flows to MODE pin.

## **Workaround**

MODE signal should be pulled low in Power-down state.